AMENDMENT TO THE SPECIFICATION

Please amend the Specification on page 10, line 12 as follows:

Rotation of gear 92 causes the second linkage 62 to slide relative to the elbow axis 8584 as indicated by the arrow 98 in Fig. 2.